



## FRONT ANCHOR DRIVERS SIDE

CANT RAIL FITMENT TO FRAME  
4 HOLES IN FROM END OF  
BRACKET  
USE M6 BOLTS SUPPLIED NOT  
 $\frac{1}{4}$  BSW